

Table 6-6 Summary of Data Logger Installation Records
EAST CONTRACT
Brightwater Conveyance System

Well I.D. ^a	Installation Date	Removal Date	Comments
BRIGHTWATER TUNNEL 1			
E-332	11/19/2004	7/25/2005	Data not recorded 3/4/2005 - 4/29/2005
E-332 s.p.	11/19/2004	7/25/2005	Data not recorded 3/4/2005 - 4/29/2005
E-345	6/15/2005	11/7/2005	Datalogger removed 8/10/2005 - 11/1/2005
E-354	12/2/2003	11/11/2004	Data not recorded 12/14/2003 - 7/19/2004
E-355	4/20/2004	11/11/2004	Data not recorded 6/18/2004 - 7/19/2004
NORTH CREEK PORTAL SITE			
P41-02A deep	12/6/2004	8/11/2005	Data not recorded 3/4/2005 - 4/29/2005; data from 12/6/2004 to 12/16/2004 reported in NCP Aquifer Test Report
P41-02A mid	11/22/2004	8/11/2005	Data not recorded 3/4/2005 - 4/29/2005; data from 12/6/2004 to 12/16/2004 reported in NCP Aquifer Test Report
P41-02A shallow	11/22/2004	8/11/2005	Data not recorded 3/4/2005 - 4/29/2005; data from 12/6/2004 to 12/16/2004 reported in NCP Aquifer Test Report
P41-04 deep	11/12/2004	1/28/2005	
P41-04 s.p.	11/12/2004	1/28/2005	
P41-04 shallow	11/12/2004	1/28/2005	Data not recorded 12/9/2004 - 1/28/2005
TREATMENT PLANT PORTAL SITE			
P46-02	6/14/2005	8/10/2005	
P46-02 s.p.	6/14/2005	8/10/2005	
NORTH CREEK CONNECTOR			
M-621 s.p.	11/12/2004	8/10/2005	

Notes:

a) "s.p." indicates datalogger monitoring data from VWP installed within standpipe

Table 6-6 Summary of Data Logger Installation Records

CENTRAL CONTRACT

Brightwater Conveyance System

Well I.D. ^a	Installation Date	Removal Date	Comments
BRIGHTWATER TUNNEL 2			
E-321 s.p.	9/26/2005	11/2/2005	Data from 9/26/2005 - 10/6/2005 reported in NKP Aquifer Test Report
E-331	11/11/2004	8/1/2005	Data not recorded 11/12/2004 - 12/16/2004, 3/4/2005 - 5/6/2005
E-331 s.p.	12/16/2004	8/1/2005	Data not recorded 3/4/2005 - 5/6/2005
BRIGHTWATER TUNNEL 3			
E-111	3/28/2003	4/8/2003	
E-112	3/24/2003	3/27/2003	
E-113 deep	6/20/2003	7/28/2005	
E-113 shallow	5/19/2003	7/28/2005	Data not recorded 7/20/2004 - 9/14/2004; questionable readings from 9/14/2004 - 12/14/2004
E-114	3/24/2003	5/3/2005	Data not recorded from 3/27/2003 - 6/20/2003, 2/11/2004 - 7/20/2004, 9/14/2004 - 11/22/2004; questionable readings from 7/21/2004 - 9/14/2004; data from 3/21/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-114 s.p.	6/20/2003	5/3/2005	Data not recorded from 2/11/2004 - 7/20/2004, 9/14/2004 - 11/22/2004; data from 3/21/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-115A deep	3/5/2004	11/7/2005	Questionable readings from 4/19/2004 - 7/20/2004; data not recorded 12/15/2004 - 1/26/2005; data from 3/21/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-115A s.p.	3/5/2004	11/7/2005	Data not recorded 12/15/2004 - 3/21/2005; data from 3/21/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-115A shallow	3/5/2004	11/7/2005	Data not recorded 12/15/2004 - 1/26/2005; data from 3/21/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-116	6/23/2003	8/10/2005	Data not recorded 5/17/2004 - 6/18/2004, 10/12/2004 - 12/15/2004
E-116 s.p.	7/10/2003	7/24/2003	
E-119 deep	9/26/2005	11/3/2005	Data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
E-120	9/26/2005	11/3/2005	Data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
E-213	6/23/2003	9/3/2003	
E-214	10/27/2003	4/26/2005	Data not recorded from 5/17/2004 - 9/14/2004, 10/12/2004 - 11/17/2004; data from 3/7/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-214 s.p.	11/28/2003	5/3/2005	Data not recorded 9/14/2004 - 10/20/2004; data from 3/7/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-215 deep	6/23/2003	8/12/2005	Questionable readings from 3/5/2004 - 9/14/2004; data not recorded 1/30/2005 - 3/1/2005; data from 3/1/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-215 shallow	6/23/2003	8/12/2005	Questionable readings from 3/22/2004 - 5/25/2004; data not recorded 1/30/2005 - 3/1/2005; data from 3/1/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-301	6/23/2003	8/7/2003	
E-302 deep	8/7/2003	11/11/2003	
E-302 shallow	8/7/2003	10/15/2003	
E-303	6/20/2003	1/29/2004	
E-304 deep	12/22/2003	5/3/2005	Data from 3/1/2005 - 3/29/2005 reported in LFP Aquifer Test Report

Table 6-6 Summary of Data Logger Installation Records**CENTRAL CONTRACT**

Brightwater Conveyance System

Well I.D. ^a	Installation Date	Removal Date	Comments
E-304 shallow	12/22/2003	5/3/2005	Data from 3/1/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-305	8/7/2003	12/14/2004	Data not recorded 10/12/2004 - 11/17/2004
E-305 s.p.	3/1/2005	4/26/2005	Data from 3/1/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-306	11/26/2003	7/26/2005	Data not recorded 9/15/2004 - 11/22/2004; data from 3/8/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-306 s.p.	12/19/2003	7/26/2005	Data from 3/8/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-307	8/7/2003	5/2/2005	Data from 3/1/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-307 s.p.	10/28/2003	3/29/2005	Data from 3/1/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-308	8/7/2003	5/3/2005	Data not recorded 10/12/2004 - 11/17/2004, 12/15/2004 - 1/26/2005; data from 3/1/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-308 s.p.	11/20/2003	5/3/2005	Data from 3/1/2005 - 3/29/2005 reported in LFP Aquifer Test Report
E-309 deep	10/28/2003	5/3/2005	Questionable readings intermittently throughout; data from 3/1/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-309 s.p.	10/28/2003	5/3/2005	Questionable readings intermittently throughout; data from 3/1/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-309 shallow	10/28/2003	5/3/2005	Questionable readings intermittently throughout; data from 3/1/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-311	8/7/2003	7/16/2004	
E-416 deep	3/22/2004	7/29/2005	Data from 3/1/2005 - 3/30/2005 reported in LFP Aquifer Test Report
E-416 shallow	3/22/2004	7/29/2005	Data from 3/1/2005 - 3/30/2005 reported in LFP Aquifer Test Report
TW-201 s.p.	12/20/2004	3/29/2005	Data not recorded 1/25/2005 - 3/1/2005; data from 3/9/2005 - 3/29/2005 reported in LFP Aquifer Test Report
TW-202 s.p.	10/1/2004	11/2/2005	Data not recorded 11/11/2004 - 12/15/2004, 3/30/2005 - 5/2/2005; piezometer replaced with a vented piezometer 12/20/04; data from 3/1/2005 - 3/30/2005 reported in LFP Aquifer Test Report
TW-202A s.p.	12/20/2004	11/2/2005	Data from 3/1/2005 - 3/30/2005 reported in LFP Aquifer Test Report
TW-203 s.p.	6/13/2005	11/3/2005	
Well #1	6/23/2003	10/22/2003	Lake Forest Park Water District Well
Well #2	6/25/2003	7/29/2005	Lake Forest Park Water District Well, datalogger removed from 10/22/2003 - 3/4/2005, data from 3/4/2005 - 3/29/2005 reported in LFP Aquifer Test Report
Well #3	7/31/2003	6/30/2004	Lake Forest Park Water District Well; data not recorded 1/19/2004 - 3/5/2004, 4/29/2004 - 6/2/2004
Well #4	7/31/2003	7/29/2005	Lake Forest Park Water District Well, data not recorded from 12/11/2003 - 3/5/2004, 4/29/2004 - 6/2/2004, 6/12/2004 - 3/8/2005, data from 3/8/2005 - 3/29/2005 reported in LFP Aquifer Test Report
Well #SW-2	7/31/2003	9/15/2003	Lake Forest Park Water District Well

Table 6-6 Summary of Data Logger Installation Records
CENTRAL CONTRACT
Brightwater Conveyance System

Well I.D. ^a	Installation Date	Removal Date	Comments
NORTH KENMORE PORTAL SITE			
P44-01 deep	11/16/2004	10/26/2005	Data not recorded 3/2/2005 - 5/2/2005, 7/29/2005 - 9/26/2005; data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
P44-01 mid	11/16/2004	10/26/2005	Data not recorded 3/2/2005 - 5/2/2005, 7/29/2005 - 9/26/2005; data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
P44-01 shallow	11/16/2004	10/26/2005	Data not recorded 3/2/2005 - 5/2/2005, 7/29/2005 - 9/26/2005; data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
P44-01 s.p.	9/14/2005	10/5/2005	Data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
P44-02 deep	9/17/2004	11/2/2005	Data not recorded 9/22/2004 - 11/16/2004, 12/16/2004 - 1/27/2005, 3/2/2005 - 9/26/2005; Data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
P44-02 mid	9/17/2004	11/2/2005	Data not recorded 9/22/2004 - 11/16/2004, 12/16/2004 - 1/27/2005, 3/2/2005 - 9/26/2005; Data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
P44-02 shallow	9/17/2004	11/2/2005	Data not recorded 9/22/2004 - 11/16/2004, 12/16/2004 - 1/27/2005, 3/2/2005 - 9/26/2005; Data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
P44-02 s.p.	9/26/2005	11/2/2005	Data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
P44-03 shallow	9/17/2004	11/2/2005	Data not recorded from 10/16/2004 - 1/27/2005, 4/13/2005 - 9/26/2005; data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
P44-03 s.p.	9/26/2005	11/2/2005	Data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
SWAMP CREEK CONNECTOR			
M-16 deep	9/17/2004	11/7/2005	Data not recorded 4/13/2005 - 9/26/2005; data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
M-16 shallow	9/17/2004	11/7/2005	Data not recorded 8/11/2005 - 9/26/2005; data from 9/26/2005 - 10/5/2005 reported in NKP Aquifer Test Report
BALLINGER WAY PORTAL SITE			
P5-04 s.p.	5/6/2005	7/28/2005	Logger malfunctioned - no data recorded

Notes:

a) "s.p." indicates datalogger monitoring data from VWP installed within standpipe

Table 6-6 Summary of Data Logger Installation Records
WEST CONTRACT
Brightwater Conveyance System

Well I.D. ^a	Installation Date	Removal Date	Comments
BRIGHTWATER TUNNEL 4			
E-101s.p.	7/1/2003	8/18/2004	
E-102	7/1/2003	6/12/2005	
E-102 s.p.	5/6/2005	11/8/2005	
E-103	6/20/2003	6/13/2005	Data not recorded 1/12/2004 - 2/25/2004, 10/13/2004 - 11/18/2004, 12/22/2004 - 1/24/2005
E-104 deep	7/31/2003	11/11/2004	Data not recorded 12/30/2003 - 3/22/2004
E-104 shallow	7/31/2003	11/11/2004	Data not recorded 12/30/2003 - 3/22/2005
E-106 s.p.	6/13/2005	11/7/2005	VWP slipped between 6/13/2005 and 8/1/2005 - data not included
E-107 deep	3/28/2003	4/5/2003	
E-107 shallow	5/6/2005	8/3/2005	
E-108 s.p.	5/5/2005	5/25/2005	
E-203	6/29/2003	11/11/2004	Data not recorded 8/5/2003 - 12/18/2003; questionable readings intermittently throughout
E-203 s.p.	7/31/2003	11/11/2004	
E-204	6/20/2003	1/31/2004	
E-205	5/19/2005	11/3/2005	Questionable data 6/9/2005 - 7/26/2005 and intermittently 7/26/2005 - 11/3/2005
E-205 s.p.	5/19/2005	11/3/2005	
E-403 s.p.	5/6/2005	11/3/2005	
E-404 s.p.	5/5/2005	11/3/2005	
POINT WELLS PORTAL SITE AND MARINE OUTFALL CONNECTOR			
P19-04	5/18/2005	11/8/2005	
P19-04 s.p.	5/18/2005	11/8/2005	
Stilling Well	4/12/2005	7/26/2005	Recording tidal fluctuation at Point Wells

Notes:

a) "s.p." indicates datalogger monitoring data from VWP installed within standpipe